-											
Work Orde		835						· ·		-	Page
Item ID: Revision ID:	D3826-041			Accept					Setup St	art	
Item Name:	Rib / Gusset A	ssembly					•		St		
Start Date: Required Date:	16/04/2010 23/04/2010	<b>Start Qty:</b> 6.00 <b>Req'd Qty:</b> 6.00			Cust Item I Customer:	D:					
Reference:			1188117 8111 1881								
Approvals:	Process Pla	n:_//	Date! D-Hel	Tooling:	Da	nte:		•			
	QC:	•	Date:	_ SPC (Y/N):	Da	ite:			31		
Sequence ID/ Work Center II	)	Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Rev	ision Nbr									
D3826	Rev	В	•					•		<b>.</b>	
		Large Fab		0.00					/-	p(m.	04.71
Large Fab		Memo		0.00				<del></del>	- — <i>G</i>		
Large Fab		rib and we	9434 to assemble D2325 supeld as per dwg D3826 A/	pport gusset together□2- R ER316 S.S. Rod	locate D2325 on	<b>**</b>	`		,	·	
		QC9- Inspect visual pe	r QSI004- Fusion Welds	0.00				<b>(</b>	Phic	66 PO	
QC		Memo	•	0.00					1510	,04 ad	
Quality Control					•						•

0.00

0.00

Sidoulzz

Quality Control

QC5- Inspect part completeness to step on W/O

Memo

Dart Aerospace L	_td
------------------	-----

W/O:			V	VORK ORD	ER CHANG	ES					İ
DATE	STEP	PROC	EDURE CH	HANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	_ Fault Ca	tegory:		_ NCI	R: Yes N	lo DQA:		_ Date: _	1
	R	esolution:								Date:	1
NCR:		W	ORK OR	DER NON-	CONFORMA	NCE	(NCR)		;		ŗ
DATE	STEP	Description of NC Section A	Initial	Corrective Action	n Description	on B	Sign &	Verificat Section		Approval Chief Eng	Approval QC Inspector
			Chief Eng		Chief Eng	٠.	Date				
					,						
									•		
				,							

April 16, 2010 11:47:22 AM

Item ID:

D3826-041

**Revision ID:** Item Name:

Rib / Gusset Assembly

**Start Date:** 

16/04/2010

Start Qty: 6.00

Accept



**Cust Item ID:** 

**Customer:** 

Setup Start

Run

Stop



**Required Date: 23/04/2010** Req'd Qty: 6.00

QC:

Reference:

Approvals:

Process Plan:

Operation

Description

Date: Date:

Tooling:

SPC (Y/N):

Date:

Date:

Start

Stop



Sequence ID/ **Work Center ID** 

130

Packaging Packaging

Memo

Memo

Set Up/ **Run Hours** 

Draw Number

**Draw** Plan Rev. Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

0.00

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

Identify as per dwg & Stock Location:

0.00

0.00

10/04/25 g MF 10-4-22

Dart Aeros	pace Ltd
------------	----------

W/O:			V	ORK ORDER CHANG	GES					• • • •
DATE	STEP	PRO	CEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									·	
					,					
Part No	•	PAR #:	Fault Ca	tegory:	NCF	R: Yes I	No DQA:		Date:	
		esolution:						1	Date:	
NCR:		V	WORK OR	DER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng	tion B	Sign & Date	Verifica Section		Approval Chief Eng	Approval QC Inspector
			Only Eng	Office Eng		Date		,		
								,		
									,	
									-	
									*	
NOTE: D			,							

## **Picklist Print**

April 16, 2010 11:47:27 AM

Work Order ID: 57835

Parent Item:

D3826-041

Parent Item Name:

Rib / Gusset Assembly

Comments:

IPP Rev:A 08-12-01 new issue DD verified by:EC



**Start Date:** 16/04/2010

**Required Date: 23/04/2010** 

Page 1

Stant Ot ... ( 00

	11 KCV.A 06-12-	-or new issue D	veri	ned by:EC					Start Qty: 6.00		Required Qty:	5.00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2235-1 Basket Rib		Manufactured	No				Each	13.0000	6.0000	Ef	0610.0	4.21
				<u>Warehou</u> Locat		Loc (	<u>Oty</u>	Loc Code				
				Main War								
				WA			13					
					57433		3					
					57593		10		$\sim$			

D3929-041

Manufactured

No

10

Each

3.0000

Gusset Assembly

Warehouse Location Main Warehouse Loc Qty

Loc Code

357600

WA

57430

3

D3929-042

Gusset Assembly

Manufactured No

3 Each


0.0000

6.0000

B57601-6)


	Dart	Aero	osp	ace	Ltd
--	------	------	-----	-----	-----

W/O:			W	ORK ORDER CHANG	ES		†		
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date C	ty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
· · · · · · · · · · · · · · · · · · ·									
	•								
Part No	:	PAR #:	Fault Cat	egory:	_ NCR: Yes N	lo DQA: _		Date:	
	R	esolution:	Dispositi	on:	_ QA: N/C Clo	sed:		Date:	
NCR:		1	NORK ORI	DER NON-CONFORMA	ANCE (NCR)				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
DATE	STEP	Description of NC	1.222.1	Corrective Action Section		Verificati	on	Approvai	Approval
	-	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	<u> </u>	Chief Eng	QC Inspector
							···		
	ı	1	1		Į.	1		l	'



Dart Aerospace Ltd
--------------------

W/O:			W	ORK ORDER CH	IANGES					
DATE	STEP	PR	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	egory:	NC	R: Yes 1	No DQA:		Date:	
		esolution:						1		
NCR:			WORK ORD	ER NON-CONFO	DRMANCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial	Corrective Action Action Descri	Section B	Sign &	Verifica Section	tion	Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng		Date	·			
I										
						:				
	1					}		1.	1	ŀ



		— <del></del>						ĺ		
W/O:			V	VORK ORDER CI	HANGES	······································				
DATE	STEP	PR	OCEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	1		O Commence of the Commence of	er f						
F					· · ·	•			yr y	.,
Part No	:	PAR #:	Fault Ca	tegory:	NC	R: Yes N	lo DQA:		_ Date: _	
		esolution:						- I	Date: _	
NCR:			WORK OR	DER NON-CONF	ORMANCI	E (NCR)				· · · · · · · · · · · · · · · · · · ·
DATE	STEP	Description of NC		Corrective Action	Section B		Verifica	tion	Approvai	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Descr Chief Eng	iption	Sign & Date	Section		Chief Eng	QC Inspector
		·			e e					r
								'	·	
					,,					
1	I			5		ı	1	1	I	1